

FORD B2103: ANTENNA NOT CONNECTED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford B2103 Code Mean?

Key on, and the PATS detected that the Antenna was not connected.

What Are The Potential Causes Of The Ford B2103 Code?

Transceiver internal antenna damaged. Replace transceiver.

Reference Sources

[PATS Job Aid Document - Motorcraft Service](#), B2103, page 2.