

FORD B2431: TRANSPONDER PROGRAMMING FAILED

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$60-\$90
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford B2431 Code Mean?

The ignition key was not programmed.

Reference Sources

[PATs Job Aid Document - Motorcraft Service](#), B2431, page 2.