

FORD P1000: OBD II MONITOR TESTING NOT COMPLETE

OVERVIEW

Severity	:	Low
DIY Difficulty Level	:	
Repair Cost	:	\$0
Can I Still Drive?	:	Yes

What Does The Ford P1000 Code Mean?

Key on or engine running; and the PCM detected one the conditions shown under Possible Causes (i. e. , this code cannot be cleared manually – it must clear itself after all of the OBD II Monitors complete).

What Are The Potential Causes Of The Ford P1000 Code?

- Battery keep alive power (KAPWR) was removed to the PCM
- One or more OBD II Monitors did not complete during an official OBD II Drive Cycle
- PCM Reset step was performed with an OBD II Scan Tool

Reference Sources

[2007 Powertrain Control Emissions Diagnosis On Board Diagnosis](#) - Sections 4: Powertrain DTC Charts and Descriptions, P1000, page 86.