

## FORD P1247: TURBOCHARGER BOOST PRESSURE LOW

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$400
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Ford P1247 Code Mean?

This DTC sets when the indicated boost pressure is less than the desired boost pressure by greater than a calibrated value for a calibrated period of time.

### What Are The Potential Causes Of The Ford P1247 Code?

- Intake air system leaks between the turbocharger and the intake manifold
- Variable geometry turbocharger (VGT) slow to respond
- VGT vanes stuck open

### Reference Sources

[ALLDATA Repair for P1247 code](#) - 2016 Ford Truck Transit 150 L5-3.2L DSL Turbo