

FORD P1248: TURBO BOOST PRESSURE NOT DETECTED

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$400
Can I Still Drive?	:	

What Does The Ford P1248 Code Mean?

Engine started, and the PCM detected a signal from the Injection Pressure sensor indicating a lack of Boost Pressure was present.

What Are The Potential Causes Of The Ford P1248 Code?

- Wastegate Control hose going to the actuator is leaking, loose or damaged
- Wastegate solenoid is damaged, sticking or it has failed
- PCM has failed

Reference Sources

[Ford P1248](#), DTCDECODE.