Ford P1289: Cylinder Head Temperature Sensor Circuit High

No

What Does The Ford P1289 Code Mean?

This DTC sets when a CHT circuit open concern is present.

What Are The Potential Causes Of The Ford P1289 Code?

- CHT circuit open
- CHT circuit short to voltage
- Damaged CHT sensor
- Damaged CHT wiring harness or connector

Reference Sources

<u>2007 Powertrain Control Emissions Diagnosis On Board Diagnosis</u> - Sections 4: Powertrain DTC Charts and Descriptions, P1289, page 99.

