

Ford P132B: Turbocharger/Supercharger Boost Control A Performance

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Intermediate

Repair Cost

:

\$100-\$400

Can I Still Drive?

:

Yes (Short-term only)

What Does The Ford P132B Code Mean?

This DTC sets when the difference between the actual manifold absolute pressure (MAP) value and the desired MAP value is greater than a calibrated threshold when the monitor runs at engine idle.

What Are The Potential Causes Of The Ford P132B Code?

- Turbocharger actuator is not responding
- Damaged MAP sensor

Reference Sources

[6.4L Power Stroke® Diesel Engine Overview for 2008 "F" Series Super Duty](#) - 2007 International Truck and Engine Corporation, P132B, page 98.