# FORD P144B: EVAP SYSTEM SECONDARY PURGE VAPOR LINE RESTRICTED/BLOCKED

#### **OVERVIEW**

Severity : Medium

DIY Difficulty Level : Intermediate

**Repair Cost** : \$150-\$300

**Can I Still Drive?** : Yes (Short-term only)

## What Does The Ford P144B Code Mean?

This DTC sets when the evaporative emission (EVAP) vent tube is restricted or blocked to the EVAP leak detection control module.

## What Are The Potential Causes Of The Ford P144B Code?

- Blockage in the fuel vapor vent hose
- Restriction in the fuel vapor vent hose
- Incorrect connections
- Damaged or corroded connections
- Damaged EVAP leak detection control module

## **Reference Sources**

Ford P144B, DTCDECODE.

