

FORD P144B: EVAP SYSTEM SECONDARY PURGE VAPOR LINE RESTRICTED/BLOCKED

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Ford P144B Code Mean?

This DTC sets when the evaporative emission (EVAP) vent tube is restricted or blocked to the EVAP leak detection control module.

What Are The Potential Causes Of The Ford P144B Code?

- Blockage in the fuel vapor vent hose
- Restriction in the fuel vapor vent hose
- Incorrect connections
- Damaged or corroded connections
- Damaged EVAP leak detection control module

Reference Sources

[Ford P144B](#), DTCDECODE.