

FORD P1550: POWER STEERING PRESSURE SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$260-\$400
Can I Still Drive?	:	No

What Does The Ford P1550 Code Mean?

KOER Self-Test enabled, and the PCM detected the PSP switch signal did not change during the self-test. This code indicates the PSP input is out of its self-test range.

What Are The Potential Causes Of The Ford P1550 Code?

- PSP switch circuit open or shorted, or the ground circuit open
- Steering wheel was not rotated during the KOER Self-Test
- PCM has failed

Reference Sources

[2007 Powertrain Control Emissions Diagnosis On Board Diagnosis](#) - Sections 4: Powertrain DTC Charts and Descriptions, P1550, page 117.