

## FORD P1710: TFT SENSOR IN-RANGE CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	No

### What Does The Ford P1710 Code Mean?

Engine started, vehicle driven to a speed over 1 mph, TFT sensor signal in-range, and the PCM did not detect any change in the TFT signal in the self-test.

### Reference Sources

[Ford P1710](#), DTCDECODE.