

## FORD P1711: TRANSMISSION FLUID TEMPERATURE SENSOR OUT OF SELF TEST RANGE

### OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	No

### What Does The Ford P1711 Code Mean?

Key on, KOER Self Test enabled; or engine running with the KOER Self Test enabled, and the PCM detected the Transmission Fluid Temperature (TFT) sensor was more than or less than the calibrated range (25°F to 240°F) during the self-test.

### Reference Sources

[Ford P1711](#), DTCDECODE.