

FORD P1712: TFT SENSOR CIRCUIT LOW INPUT

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	No

What Does The Ford P1712 Code Mean?

Engine started, and the PCM detected the TFT sensor signal was less than 0.2v (equivalent to a temperature of more than 357°F).

Reference Sources

[Ford P1712](#), DTCDECODE.