

Ford P1780: Transmission Control Switch (O/D Cancel) Circuit Out Of Self Test Range

OVERVIEW

Severity

:

High

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$300-\$800

Can I Still Drive?

:

No

What Does The Ford P1780 Code Mean?

Engine started, KOER Self-Test enabled, and the PCM detected the Transmission Control Switch (TCS) was out of range during the test.

What Are The Potential Causes Of The Ford P1780 Code?

The Tow/Haul select switch failed during the KOER self-test.

Reference Sources

[2007 Powertrain Control Emissions Diagnosis On Board Diagnosis](#) - Sections 4: Powertrain DTC Charts and Descriptions, P1780, page 124.