

GMC P113A: EXHAUST GAS TEMPERATURE SENSORS 3-4 NOT PLAUSIBLE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$50-\$1550
Can I Still Drive?	:	No

What Does The GMC P113A Code Mean?

The ECM detects, at engine start, that a temperature difference of greater than 30°C (54°F), exists between exhaust gas temperature sensor 3 and exhaust gas temperature sensor 4.

Conditions for setting the code:

- [P113A](#), [P0112](#), [P0113](#), [P242C](#), [P242D](#), [P2470](#), or [P2471](#) is not set.
- The ignition has been OFF for greater than 8 hours.
- The engine is running.
- The ambient air temperature is greater than -60°C (-76°F).
- DTC P113A runs once per key cycle when the above conditions are met.

Reference Sources

[GMC P113A](#), DTCDECODE.