

GMC P1191: INTAKE AIR DUCT LEAK

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The GMC P1191 Code Mean?

Conditions for Setting the DTC.

DTCs [P0405](#), [P0406](#), [P0102](#) and [P0103](#) are not set.

All EGR tests have been completed (internal to PCM). Intake leak greater than calibrated value (internal to PCM)

What Are The Potential Causes Of The GMC P1191 Code?

The most likely cause of failure is a leaky intake duct after the MAF sensor. To run the diagnostic test the engine must be at operating temperature, vehicle in drive at idle for approximately 1 minute, then with vehicle in park hold engine rpm steady bet

Reference Sources

[Technical Service Bulletin PIP5094 for P1191](#) - General Motors, February 2023