

What Does The GMC P159C Code Mean?

The engine is running and PTO is engaged.

What Are The Potential Causes Of The GMC P159C Code?

- The PTOM detects a signal mismatch between the remote engine shut off signal and the PTO engine shutdown signal.
- The above condition is present for greater than a predetermined time threshold.

Reference Sources

ProDemand Automotive Repair Information for P159C - 2020 GMC Sierra 2500 HD Base