GMC P179B: RANGE STATE COMMAND CIRCUIT		
		OVERVIEW
Severity	:	Hig
DIY Difficulty Level	:	Advance
Repair Cost	:	\$500-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The GMC P179B Code Mean?

The engine is running. Ignition voltage is 8-18 V.

What Are The Potential Causes Of The GMC P179B Code?

The control solenoid valve assembly has detected a Range State Command rolling count error for 0.2 seconds.

Reference Sources

<u>13 OBDG06 Hybrid Diagnostics for P179B</u> - General Motors, page 269.

