

## GMC P179B: RANGE STATE COMMAND CIRCUIT

### OVERVIEW

|                      |   |                       |
|----------------------|---|-----------------------|
| Severity             | : | High                  |
| DIY Difficulty Level | : | Advanced              |
| Repair Cost          | : | \$500-\$900           |
| Can I Still Drive?   | : | Yes (Short-term only) |

### What Does The GMC P179B Code Mean?

The engine is running. Ignition voltage is 8-18 V.

### What Are The Potential Causes Of The GMC P179B Code?

The control solenoid valve assembly has detected a Range State Command rolling count error for 0.2 seconds.

### Reference Sources

[13 OBDG06 Hybrid Diagnostics for P179B](#) - General Motors, page 269.