| CIRCUIT MALFUNCTION | | | |
|----------------------|---------|--------------|------|
| OVERVIEW | | | |
| Severity | : | | High |
| DIY Difficulty Level | : | Intermediate | |
| Repair Cost | : \$200 | -\$350 | |

What Does The GMC P1815 Code Mean?

No VSS DTCs <u>P0502</u> or <u>P0503</u>. The transmission OSS is less than 250 RPM. The engine speed is in transition from 0 RPM to greater than 625 RPM.

Reference Sources

Technical Service Bulletin PIP5094 for P1815 - General Motors

