GMC P1831: PRESSURE CONTROL (PC)/SHIFT LOCK SOLENOID CONTROL CIRCUIT LOW VOLTAGE OVERVIEW Severity : High DIY Difficulty Level : Intermediate Repair Cost : \$150-\$250 Can I Still Drive? : No

What Does The GMC P1831 Code Mean?

The engine speed is greater than 500 RPM. Ignition voltage is between 8-18 volts. High side driver 2 is enabled. DTC P1831 has not failed this ignition.

Reference Sources

Technical Service Bulletin PIP5094 for P1831 - General Motors

