

HONDA B1078: DAYTIME RUNNING LIGHTS SYSTEM ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Honda B1078 Code Mean?

Daytime Running Lights inoperable.

What Are The Potential Causes Of The Honda B1078 Code?

- Blown fuse No. 1 (10 A) and No. 2 (10 A) in the under-hood fuse/relay box
- Faulty bulbs
- Poor continuity between daytime running light 2P connector terminal No. 2 and under-hood fuse/relay box connector G (4P) terminals No. 1 and No. 2 respectively.
- Open in the BLK wire or poor ground (G201-right side, G301-left side)
- Faulty Relay Control Module

Reference Sources

[Body Electrical Repair Information for B1078](#) - American Honda Motor, page 173.