

HONDA B1225: OPEN IN THE IN-CAR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Honda B1225 Code Mean?

Poor communication between the Temperature Sensor and the Climate Control Unit. ("Open") condition.

What Are The Potential Causes Of The Honda B1225 Code?

- Perform the HVAC self-diagnostic function with the HDS
- Loose wires or poor connections on the in-car temperature sensor circuit
- "Open" circuit between the Climate Control Unit and the in-car temperature sensor
- Faulty In-car Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[Body Electrical Repair Information for B1225](#) - American Honda Motor, page 88.