

HONDA B1226: SHORT IN THE IN-CAR TEMPERATURE SENSOR CIRCUIT

OVERVIEW

| | | |
|----------------------|---|------------------------------------|
| Severity | : | <div><div>Medium</div></div> |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost | : | \$100-\$250 |
| Can I Still Drive? | : | Yes (Short-term only) |

What Does The Honda B1226 Code Mean?

Poor communication between the In-car Temperature Sensor and the Climate Control Unit. ("Short") circuit.

What Are The Potential Causes Of The Honda B1226 Code?

- Perform the HVAC self-diagnostic function with the HDS
- "Short" in the wires between the Climate Control Unit and the in-car temperature sensor
- Faulty In-car Temperature Sensor
- Faulty Climate Control Unit

Reference Sources

[Body Electrical Repair Information for B1226](#) - American Honda Motor, page 88.