

HONDA B2969: CLIMATE CONTROL UNIT LOST COMMUNICATION WITH MICU (WIPSW MESSAGE)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Honda B2969 Code Mean?

Do the Self-Diagnostic Function with the HDS.

What Are The Potential Causes Of The Honda B2969 Code?

- Go to MICU DTC U1280 troubleshooting
- Check for loose wires or poor connections on the MICU and the climate control unit circuit

Reference Sources

[2007-09 HVAC Climate Control Repair Information for B2969](#) - 2008 Acura MDX, pages 108-109.