HONDA P15AE: CYLINDER PAUSE SIGNAL MALFUNCTION			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$120-\$500	
Can I Still Drive?	:	No	

What Does The Honda P15AE Code Mean?

With the ignition switch ON, P16C9 not active, the SCP signal input value differs from the PCM out put value (received by the CAN communication) for at least 2.6 seconds.

NOTE: Before you troubleshoot, record all freeze data and any on-board snapshots, and review the general troubleshooting information.

What Are The Potential Causes Of The Honda P15AE Code?

- Poor connections or loose terminals at the engine mount control unit and the rocker arm oil control solenoid
- Open circuit betwenn the PCM and the engine mount control unit
- Faulty engine mount control unit

Reference Sources

Honda DTC Codes Reference for P15AE - Page 8.

