

HONDA P1730: PROBLEM IN SHIFT CONTROL SYSTEM

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$100-\$1000
Can I Still Drive?	:	No

What Are The Potential Causes Of The Honda P1730 Code?

- Low or dirty transmission fluid
- Repair the hydraulic system related to shift valves A, B, and D, or replace the transmission

Reference Sources

[2007 Honda Element EX Service Manual for P1730](#) - Pages 240-242.