

HONDA P1747: HYDRAULIC CONTROL SYSTEM (CUT VALVE A STUCK ON OR CUT VALVE B STUCK OFF)

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$500
Can I Still Drive?	:	No

What Are The Potential Causes Of The Honda P1747 Code?

- Low or dirty transmission fluid
- Inspect the strainer for metal debris or excessive clutch material, if present replace the transmission
- Faulty cut valve A in the servo body, cut valve B in the main valve body, or replace the main valve body

Reference Sources

[Honda P1747](#), DTCDECODE.