HONDA U1221: INVALID DATA RECEIVED FROM DC-DC CONVERTER CONTROL MODULE

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$75-\$200

Can I Still Drive? : Yes

What Are The Potential Causes Of The Honda U1221 Code?

- Motor Control Module (MCM) SCIDM serial line open
- Motor Control Module (MCM) SCIDM serial line Short to ground
- DC-DC converter failure
- Motor Control Module (MCM)/Battery Condition Monitor (BCM) failure

Reference Sources

Honda U1221, DTCDECODE.

