

HONDA U1221: INVALID DATA RECEIVED FROM DC-DC CONVERTER CONTROL MODULE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Are The Potential Causes Of The Honda U1221 Code?

- Motor Control Module (MCM) SCIDM serial line open
- Motor Control Module (MCM) SCIDM serial line Short to ground
- DC-DC converter failure
- Motor Control Module (MCM)/Battery Condition Monitor (BCM) failure

Reference Sources

[Honda U1221](#), DTCDECODE.