

# Hyundai B1101: SRSCM Input Voltage High

## OVERVIEW

Severity

:

Medium

DIY Difficulty Level

:

Advanced

Repair Cost

:

\$600-\$720

Can I Still Drive?

:

**Yes** (Short-term only)

## What Does The Hyundai B1101 Code Mean?

Enable Conditions Ignition "ON" Threshold Value B1101 16.5V < Vbat B1102 Vbat < 10.6V

Diagnostic Time Qualification More than 4 sec De-Qualification More than 4 sec.

## What Are The Potential Causes Of The Hyundai B1101 Code?

- Poor connection of connected part.
- Open/Short circuit in power harness.
- Open/Short circuit in ground harness.
- Faulty charging system.
- Faulty SRSCM.

## Reference Sources

[SRSCM \(SRS Control Module\) General Information for B1101](#) - Hyundai Genesis Coupe, pages 50-52.