

HYUNDAI B1305: YAW RATE SENSOR SIGNAL FAULT

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$550-\$750
Can I Still Drive?	:	No

What Does The Hyundai B1305 Code Mean?

AFLS ECU set this code If input value(yaw rate sensor's signal) is out of available range.

What Are The Potential Causes Of The Hyundai B1305 Code?

- CAN communication circuit Open/Short
- Yaw rate circuit Open/Short
- Faulty Yaw rate

Reference Sources

[Hyundai B1305](#), DTCDECODE.