

HYUNDAI B1473: DRIVER CURTAIN AIRBAG (CAB) CIRCUIT RESISTANCE HIGH

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$700
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B1473 Code Mean?

Enable Conditions Ignition "ON" Threshold Value B1473 and [B1477](#) CAB resistance $\geq 5.7\Omega$ [B1474](#) and [B1478](#) CAB resistance $\leq 1.3\Omega$ Diagnostic Time Qualification More than 4 sec De-Qualification More than 8 sec

What Are The Potential Causes Of The Hyundai B1473 Code?

- Poor connection of connected part.
- Poor connection between shorting bar and release pin.
- Faulty CAB.
- Faulty SRSCM.

Reference Sources

[SRSCM \(SRS Control Module\) General Information for B1473](#) - Hyundai Genesis Coupe, pages 203-205.