

HYUNDAI B1475: DRIVER CURTAIN AIRBAG (CAB) CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$200-\$700
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B1475 Code Mean?

Curtain Airbag (hereinafter referred to CAB) is located at driver and passenger side of headliner. It protects passenger's head and shoulder from fragments of glass or something sharpen caused by overturn. CAB consists of air bag and inflator. Air bag reduces impact of collision by filling up gas. Inflator keeps gas and uses it to deploy air bag on collision.

The SRSCM sets DTC B1475 if there is a short to ground in DCAB harness. *In this case, SRSCM checks if there's any fault in circuit by sending current for a while.

What Are The Potential Causes Of The Hyundai B1475 Code?

- Short to ground in CAB harness.
- Poor connection of connected part.
- Poor connection between shorting bar and release pin.
- Faulty CAB.
- Faulty SRSCM.

Reference Sources

[SRSCM \(SRS Control Module\) General Information for B1475](#) - Hyundai Genesis Coupe, pages 206-212.