

HYUNDAI B2514: EXTERNAL TAIL LAMP RH CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$20-\$100
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B2514 Code Mean?

Once BCM receives Tail Lamp switch working signal, it sends the signal to SJB by CAN communication. SJB turns on Tail Lamp. This code is set when Right External Tail Lamp circuit is shorted to ground for more than 150ms during right External Tail Lamp operating.

What Are The Potential Causes Of The Hyundai B2514 Code?

- Poor connection
- Short to ground in Right External Tail Lamp circuit
- Faulty Right External Tail Lamp
- Faulty SJB

Reference Sources

[Hyundai B2514](#), DTCDECODE.