

HYUNDAI B2515: EXTERNAL TAIL LAMP LH CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$20-\$100
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B2515 Code Mean?

Once BCM receives Tail Lamp switch working signal, it sends the signal to SJB by CAN communication. SJB turns on Tail Lamp. This code is set when Left External Tail Lamp External Tail Lamp circuit is shorted to ground for more than 150ms during Left External Tail Lamp External Tail Lamp operating.

What Are The Potential Causes Of The Hyundai B2515 Code?

- Poor connection
- Short to ground in Left External Tail Lamp circuit
- Faulty Left External Tail Lamp
- Faulty SJB

Reference Sources

[Technical Service Bulletin for B2515](#) - Hyundai Sonata