

HYUNDAI B2517: INTERNAL TAIL LAMP CIRCUIT SHORT TO GROUND

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$20-\$100
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B2517 Code Mean?

Once BCM receives Tail Lamp switch working signal, it sends the signal to SJB by CAN communication. SJB turns on Tail Lamp. This code is set when Internal Tail Lamp circuit is shorted to ground for more than 150ms during Internal Tail Lamp operating.

What Are The Potential Causes Of The Hyundai B2517 Code?

- Poor connection
- Short to ground in Internal Tail Lamp circuit
- Faulty Internal Tail Lamp
- Faulty SJB

Reference Sources

[Hyundai B2517](#), DTCDECODE.