HYUNDAI B2598: RIGHT REAR BLOWER SWITCH ILLUMINATION CIRCUIT GROUND

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$25-\$150

Can I Still Drive? : Yes (Short-term only)

What Are The Potential Causes Of The Hyundai B2598 Code?

- Open in power circuit
- Light bulb failure

Reference Sources

Hyundai B2598, DTCDECODE.

