

HYUNDAI B2837: GPS MODULE CONNECTION ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai B2837 Code Mean?

The TMU sets B2837 when GPS antenna has been disconnected or the communication is interrupted between main CPU and GPS module.

What Are The Potential Causes Of The Hyundai B2837 Code?

- Open in GPS antenna circuit
- Short in GPS antenna circuit
- Antenna
- TMU

Reference Sources

[Hyundai B2837](#), DTCDECODE.