HYUNDAI C1604: EPS ECU HARDWARE ERROR			
		OVERVIEW	
Severity	:	Medium	
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$800-\$1300	
Can I Still Drive?	:	Yes (Short-term only)	

What Does The Hyundai C1604 Code Mean?

EPS CM checks operating condition of H/W periodically. EPS CM sets this code and turns on warning lamp if there is a fault in H/W. At that time EPS CM inhibits EPS opreation.

What Are The Potential Causes Of The Hyundai C1604 Code?

- Faulty MCU
- Faulty memory

Reference Sources

General Troubleshooting Information for C1604- Hyundai GENESIS COUPE, pages 333-334.

