HYUNDAI P1521: POWER STEERING SWITCH INPUT CIRCUIT MALFUNCTION

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$150-\$250

Can I Still Drive? : Yes (Short-term only)

What Are The Potential Causes Of The Hyundai P1521 Code?

- Power steering pressure switch circuit open, shorted to ground, shorted to VREF, or shorted to system power (B+)
- Power steering pressure switch is damaged or has failed
- PCM has failed

Reference Sources

Hyundai P1521, DTCDECODE.

