

HYUNDAI P1521: POWER STEERING SWITCH INPUT CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Hyundai P1521 Code?

- Power steering pressure switch circuit open, shorted to ground, shorted to VREF, or shorted to system power (B+)
- Power steering pressure switch is damaged or has failed
- PCM has failed

Reference Sources

[Hyundai P1521](#), DTCDECODE.