

## HYUNDAI P1675: TRANSPONDER PROGRAMMING ERROR

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$60-\$90
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Hyundai P1675 Code Mean?

Enable Conditions IG ON(During the authentication) Threshold value Invalid characteristic data No transponder or more than two transponder is detected by coil antenna Detecting time Immediately

### What Are The Potential Causes Of The Hyundai P1675 Code?

Invalid transponder.

### Reference Sources

[General Troubleshooting Information for P1675](#)- Hyundai GENESIS COUPE, pages 386-388.