

HYUNDAI P1693: TRANSPONDER NO RESPONSE ERROR/INVALID RESPONSE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$60-\$90
Can I Still Drive?	:	Yes (Short-term only)

What Does The Hyundai P1693 Code Mean?

Enable Conditions IG ON Threshold value Corrupted data from Transponder More than one TP in the magnetic field No TP(Key without TP) in the magnetic field

What Are The Potential Causes Of The Hyundai P1693 Code?

Invalid transponder.

Reference Sources

[General Troubleshooting Information for P1693](#)- Hyundai GENESIS COUPE, pages 405-407.