

HYUNDAI P1709: A/T KICK DOWN SERVO SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$170-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Hyundai P1709 Code?

- Kick Down servo switch circuit open between switch and PCM
- Kick Down servo switch circuit is shorted to ground
- Kick Down servo switch is damaged or has failed
- TCM has failed

Reference Sources

[Hyundai P1709](#), DTCDECODE.