

INFINITI B2128: UART COMMUNICATION LINE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$50-\$400
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti B2128 Code Mean?

The communication between driver seat control unit and automatic drive positioner control unit is interrupted for a period of time.

What Are The Potential Causes Of The Infiniti B2128 Code?

- UART communication line
- – UART communication line is open or shorted
- Driver seat control unit
- Automatic drive positioner control unit

Reference Sources

[INFINITI QX56 2010 Service Manual for B2128](#)