

## INFINITI C1110: ABS CONTROLLER AND ELECTRIC UNIT (CONTROL UNIT)

### OVERVIEW

Severity	:	<div><div></div></div> High
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes

### What Does The Infiniti C1110 Code Mean?

When there is an internal malfunction in the ABS actuator and electric unit (control unit) or wheel speed sensor.

### What Are The Potential Causes Of The Infiniti C1110 Code?

ABS actuator and electric unit (control unit)

### Reference Sources

[Brake Control System Repair Information for C1110](#) - 2008 Infiniti FX35/FX45, page 27.