

INFINITI C1121: LF OUT ABS SOLENOID

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes

What Does The Infiniti C1121 Code Mean?

When the control unit detects a malfunction in the front LH outlet solenoid circuit.

What Are The Potential Causes Of The Infiniti C1121 Code?

- Harness or connector
- ABS actuator and electric unit (control unit)
- Fusible link
- Battery power supply system

Reference Sources

[Brake Control System Repair Information for C1121](#) - 2008 Infiniti FX35/FX45, page 27.