

INFINITI P1137: SWIRL CONTROL VALVE CONTROL POSITION SENSOR CIRCUIT MALFUNCTION:

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$300-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti P1137 Code Mean?

Engine running at idle speed, and the PCM detected an excessively high or low signal from the SCV Control Position sensor circuit.

What Are The Potential Causes Of The Infiniti P1137 Code?

- Swirl Control valve control position sensor open or shorted
- Swirl Control valve control position sensor is damaged
- Swirl Control valve control position sensor has failed
- PCM has failed

Reference Sources

[Infiniti P1137](#), DTCDECODE.