

INFINITI P1165: SWIRL CONTROL VALVE CONTROL VACUUM CHECK SWITCH:

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$300-\$900
Can I Still Drive?	:	Yes (Short-term only)

What Does The Infiniti P1165 Code Mean?

Engine started, ECT sensor from 59-122°F, and the PCM detected an unexpected voltage condition on the Swirl Control circuit during the CCM test.

What Are The Potential Causes Of The Infiniti P1165 Code?

- SCV vacuum hoses are switched or disconnected
- SCV control vacuum switch circuit is opened or shorted
- SCV control vacuum switch is damaged or has failed
- SCV solenoid is damaged or has failed

Reference Sources

[Infiniti P1165](#), DTCDECODE.